

WHS-PRO-008 Asbestos Management Procedure

Appendix 3 – Air Monitoring Action Levels



1. Investigate

Investigate the cause.

Ai11.3f 10.0P <</MCID 0 >>BDC 11.04 -0 0 m29j EMC /P <</MA11.037.84960 0 .8P <2 cm /1C /P <</Mr9o 0.08

	<p>2. Implement</p>	<p>Implement controls to eliminate or minimise exposure and prevent further release.</p>

More than 0.02